



Des.	Pos.	Description
C544	E 8	Connector, 21-pole
C545	F 8	Connector, 12-pole
C572	B 7	Connector, 62-Pole
C584	E 5	Connector charging interface
C619	E 7	Connector, 25-pole
C625	C 7	Connector, 62-pole
C683	B 7	Splice, CMD
C686	D 7	Connector, 62-pole
C817	B 7	Connector, 62-pole
C8281	A 7	Connector, 16-pole
C8401	D 7	Junction box, 8-pole
E172	E 4	Control unit, battery slave unit
E181	D 7	Control unit, EVCC, CMD
G593	C 7	Ground Splice, S-BRU
G597	C 7	Ground Point, S-BRU
G823	D 6	Ground Point, S-BRU CCS
M73	F 7	Motor, lock device
F508	C 5	Central electric unit, VCB
F513	A 7	Central electric unit, chassis
R125	D 4	Contactors, box
S661	F 7	Switch, Abort charging

**SCANIA**

Circuit Diagram:

**CMD**

Drawing No.- 2890987-1-5  
 Sheet-Rev.

N.B. The copyright and ownership of this drawing including associated computer data are and will remain ours. They must not be copied, used or brought to the attention of any third party without prior permission (C) Scania, Sweden