



## Products affected

Truck			Bus			Power Solutions			
4	PGRT	LPGRS	4	FKN	CK	P93	P96	E2011	PS2024
-	-	X	-	-	X	-	-	-	-

Miscellaneous:

## Assembly tool 3 151 712 missing screw for working with preload of differential bearings

### Background

*Assembly tool gauge 3 151 712* – missing a screw to attach *Gauge 3 166 409*.

### Production solution

The screw will be introduced as a Scania part. Design work has been initiated. This TI is valid until the solution is implemented.

### Service solution


Order the screw locally to solve the problem until *Assembly tool gauge 3 151 712* is updated with a screw inserted on the Scania number.

Supplier: Ravema AB Hoffman Group, supplier part number: 434825-8 (5 items included).

### Work description

Refer to *the Workshop manual 08 Rear axle > 08-05 Axle gear > Central gear R756 and RB756*.

1. Place 434825-8 between 3 151 712 and 3 166 409 to attach the dial gauge.





For more information see FQ477806.