



Products affected

Truck			Bus			Engine (I&M)		
4	PGRT	LPGRS	4	FKN	CK	P93	P96	E2011
-	-	X	-	-	-	-	-	-

Miscellaneous:

Shortage of electric compressors for auxiliary cab cooler


Background

There will probably be a shortage of electric compressors for auxiliary cab coolers at the beginning of November 2021. In production, some vehicles will be fitted with a dummy instead of an auxiliary cab cooler.

Regardless of whether the vehicle is produced with or without a dummy, the SOPS file will be missing certain information for this system.

Production solution

Some vehicles will be fitted with a dummy instead of an auxiliary cab cooler. There will be a red tag on the dummy with the text *Not intended for production*.



444 536



444 537



Service solution

On vehicles produced with the correct compressor, spare part programming for SDP3 needs to be carried out.

Vehicles with a dummy will need to be supplemented with a compressor in an upcoming campaign as soon as parts are available.

Parts

Designation	Part	Quantity
Electric compressor	2 091 525 ^a	1
Auxiliary cab cooler	2 824 336	1

a. Replaced by a dummy.