



## Products affected

Truck			Bus			Power Solutions			
4	PGRT	LPGRS	4	FKN	CK	P93	P96	E2011	PS2024
-	X	X	-	-	-	-	-	-	-

Miscellaneous:

## Function test throttle, OTTO

### Background

Several gas cars have had their throttles replaced due to diagnostic trouble codes (DTCs), even though the throttles are working properly. A function wizard for the wrong throttle has been carried out and shown negative results. The throttle has then been replaced without it being necessary.

### Service solution

To check the function of the throttle on OTTO cars, you can activate the throttle blade by pressing the accelerator pedal when the starter key is in ignition timing (engine off). One person presses the accelerator pedal while another person visually inspects the throttle blade to ensure that it is moving freely.

#### **WARNING!**

Do not put your fingers into the trottlet.

#### **NOTE:**

The throttle will not be fully closed during this test. It will be able to move between approx. 10% to 90% open.